

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report December 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C		DEV agar after 44 ± 4 h at 36 ± 2 °C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110776570	Drinking water Delivery Tap 1	14.12.2011	10:58	13,7	colorless, clear	1,03	0		0		0	0	0
110776571	Drinking water Delivery Tap 2	14.12.2011	10:55	13,5	colorless, clear	0,56	0		0		0	0	0
110776572	Drinking water Delivery Tap 3	14.12.2011	10:52	13,0	colorless, clear	0,60	0		0		0	0	0
110776573	Drinking water Delivery Tap 4	14.12.2011	10:46	14,0	colorless, clear	1,68	0		0		0	0	0
110776574	Tank vehicle KWW 28, clutch pipe delivery	14.12.2011	10:34	14,4	colorless, clear	1,58	0		0		0	0	0
110776575	Tank vehicle KWW 29, clutch pipe delivery	14.12.2011	10:12	11,6	colorless, clear	0,78	0		0		0	0	0
110776576	Tank vehicle KWW 30, clutch pipe delivery	14.12.2011	10:27	13,0	colorless, clear	0,91	0		0		0	0	0
110776577	Tank vehicle KWW 31, clutch pipe delivery	14.12.2011	10:32	13,3	colorless, clear	0,95	0		0		0	0	0
110776578	Tank vehicle KWW 32, clutch pipe delivery	14.12.2011	10:06	13,2	colorless, clear	0,97	0		0		0	0	0
110776579	Tank vehicle KWW 33, clutch pipe delivery	14.12.2011	10:03	13,4	colorless, clear	0,99	0		0		0	0	0
110776580	Tank vehicle KWW 34, clutch pipe delivery	14.12.2011	10:08	13,4	colorless, clear	0,89	0		1		0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report December 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
110776581	Tank vehicle KWW 35, clutch pipe delivery	14.12.2011	10:42	13,0	colorless, clear	0,49	0	0	0	0	0
110776582	Tank vehicle KWW 36, clutch pipe delivery	14.12.2011	10:30	11,8	colorless, clear	0,64	0	0	0	0	0
110776583	Tank vehicle KWW 37, clutch pipe delivery	14.12.2011	10:14	12,7	colorless, clear	0,50	0	0	0	0	0
110776584	Tank vehicle KWW 38, clutch pipe delivery	14.12.2011	10:48	12,1	colorless, clear	0,77	0	0	0	0	0
110776585	Tank vehicle KWW 39, clutch pipe delivery	14.12.2011	10:10	12,7	colorless, clear	0,99	0	0	0	0	0
110776586	Tank vehicle KWW 40, clutch pipe delivery	14.12.2011	10:39	13,7	colorless, clear	0,78	0	0	0	0	0
110776587	Tank vehicle KWW 41, clutch pipe delivery	14.12.2011	10:15	12,8	colorless, clear	1,02	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, December 21, 2011
