

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report April 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C		DEV agar after 44 ± 4 h at 36 ± 2°C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110191224	Drinking water Delivery Tap 1	26.04.2011	12:56	17,5	colorless, clear	0,85	0		0		0	0	0
110191225	Drinking water Delivery Tap 2	26.04.2011	12:58	19,6	colorless, clear	0,99	0		0		0	0	0
110191226	Drinking water Delivery Tap 3	26.04.2011	13:01	16,7	colorless, clear	0,95	0		0		0	0	0
110191227	Drinking water Delivery Tap 4	26.04.2011	13:05	18,7	colorless, clear	1,04	0		0		0	0	0
110191228	Tank vehicle KWW 28, clutch pipe delivery	26.04.2011	12:20	17,7	colorless, clear	0,17	0		0		0	0	2
110191230	Tank vehicle KWW 30, clutch pipe delivery	26.04.2011	12:22	18,2	colorless, clear	1,25	0		0		0	0	0
110191231	Tank vehicle KWW 31, clutch pipe delivery	26.04.2011	12:29	18,6	colorless, clear	0,28	0		0		0	0	0
110191232	Tank vehicle KWW 32, clutch pipe delivery	26.04.2011	12:53	19,5	colorless, clear	0,59	0		0		0	0	1
110191233	Tank vehicle KWW 33, clutch pipe delivery	26.04.2011	12:40	17,9	colorless, clear	0,91	0		0		0	0	0
110191234	Tank vehicle KWW 34, clutch pipe delivery	26.04.2011	12:05	18,4	colorless, clear	0,71	0		0		0	0	0
110191235	Tank vehicle KWW 35, clutch pipe delivery	26.04.2011	12:48	20,6	colorless, clear	< 0,03	0		0		0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report April 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C		DEV agar after 44 ± 4 h at 36 ± 2 °C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110191236	Tank vehicle KWW 36, clutch pipe delivery	26.04.2011	12:26	18,6	colorless, clear	0,75	0	0	0	0	0	0	0
110191237	Tank vehicle KWW 37, clutch pipe delivery	26.04.2011	12:32	18,2	colorless, clear	0,44	0	0	0	0	0	0	0
110191238	Tank vehicle KWW 38, clutch pipe delivery	26.04.2011	12:10	19,5	colorless, clear	< 0,03	0	0	0	0	0	0	0
110191239	Tank vehicle KWW 39, clutch pipe delivery	26.04.2011	12:46	18,3	colorless, clear	0,73	0	0	0	0	0	0	0
110191240	Tank vehicle KWW 40, clutch pipe delivery	26.04.2011	12:24	18,2	colorless, clear	1,00	0	0	0	0	0	0	0
110191241	Tank vehicle KWW 41, clutch pipe delivery	26.04.2011	12:37	19,3	colorless, clear	< 0,03	0	0	0	0	0	0	3

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing samples **110191228**, **110191232** and **110191241** out of limit value: **Pseudomonas aeruginosa**

The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, april 29, 2011
