

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report August 2011**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C		DEV agar after 44 ± 4 h at 36 ± 2°C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110468053	Drinking water Delivery Tap 1	03.08.2011	09:55	18,9	colorless, clear	0,53	0		0		0	0	0
110468054	Drinking water Delivery Tap 2	03.08.2011	09:58	18,9	colorless, clear	0,34	0		0		0	0	0
110468055	Drinking water Delivery Tap 3	03.08.2011	10:01	18,7	colorless, clear	0,84	0		0		0	0	0
110468056	Drinking water Delivery Tap 4	03.08.2011	10:05	18,9	colorless, clear	0,45	0		0		0	0	0
110468057	Tank vehicle KWW 28, clutch pipe delivery	03.08.2011	09:42	20,1	colorless, clear	0,55	0		0		0	0	0
110468058	Tank vehicle KWW 29, clutch pipe delivery	03.08.2011	09:38	22,3	colorless, clear	0,76	0		0		0	0	0
110468059	Tank vehicle KWW 30, clutch pipe delivery	03.08.2011	09:22	23,4	colorless, clear	0,37	0		0		0	0	0
110468060	Tank vehicle KWW 31, clutch pipe delivery	03.08.2011	09:50	21,7	colorless, clear	0,68	0		0		0	0	0
110468091	Tank vehicle KWW 32, clutch pipe delivery	03.08.2011	09:35	21,1	colorless, clear	0,44	0		0		0	0	71
110468092	Tank vehicle KWW 33, clutch pipe delivery	03.08.2011	09:05	21,5	colorless, clear	0,85	0		0		0	0	0
110468093	Tank vehicle KWW 34, clutch pipe delivery	03.08.2011	09:29	21,3	colorless, clear	0,84	0		0		0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report August 2011**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C		DEV agar after 44 ± 4 h at 36 ± 2 °C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110468094	Tank vehicle KWW 35, clutch pipe delivery	03.08.2011	09:20	22,7	colorless, clear	0,71	0		0		0	0	0
110468095	Tank vehicle KWW 36, clutch pipe delivery	03.08.2011	09:45	22,1	colorless, clear	0,64	0		0		0	0	0
110468096	Tank vehicle KWW 37, clutch pipe delivery	03.08.2011	09:26	19,5	colorless, clear	0,66	0		0		0	0	0
110468097	Tank vehicle KWW 38, clutch pipe delivery	03.08.2011	09:35	23,8	colorless, clear	0,60	0		0		0	0	0
110468098	Tank vehicle KWW 39, clutch pipe delivery	03.08.2011	09:10	20,7	colorless, clear	0,86	0		0		0	0	0
110468134	Tank vehicle KWW 40, clutch pipe delivery	03.08.2011	09:32	19,5	colorless, clear	0,67	0		0		0	0	0
110468135	Tank vehicle KWW 41, clutch pipe delivery	03.08.2011	09:17	19,9	colorless, clear	1,05	0		0		0	0	0

**Assessment:**

According to the investigations of the German Drinking Water Regulation the following parameter of the testing samples **110468091** out of limit value: **Pseudomonas aeruginosa**  
 The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

**SGS INSTITUT FRESENIUS GmbH**

Taunusstein, august 08, 2011