

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500287891
Report February 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C		DEV agar after 44 ± 4 h at 36 ± 2°C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110050669	Drinking water Delivery Tap 1	23.02.2011	10:02	13,5	colorless, clear	0,81	0	0	0	0	0	0	0
110050670	Drinking water Delivery Tap 2	23.02.2011	10:00	14,7	colorless, clear	0,85	0	0	0	0	0	0	0
110050671	Drinking water Delivery Tap 3	23.02.2011	09:58	14,9	colorless, clear	0,74	0	0	0	0	0	0	0
110050672	Drinking water Delivery Tap 4	23.02.2011	09:55	14,2	colorless, clear	1,33	0	0	0	0	0	0	0
110050673	Tank vehicle KWW 28, clutch pipe delivery	23.02.2011	09:15	12,0	colorless, clear	0,47	0	0	0	0	0	0	0
110050674	Tank vehicle KWW 29, clutch pipe delivery	23.02.2011	09:21	13,2	colorless, clear	0,63	0	0	0	0	0	0	0
110050675	Tank vehicle KWW 30, clutch pipe delivery	23.02.2011	09:22	12,0	colorless, clear	0,39	0	0	0	0	0	0	0
110050676	Tank vehicle KWW 31, clutch pipe delivery	23.02.2011	09:52	5,9	colorless, clear	0,40	0	0	0	0	0	0	0
110050677	Tank vehicle KWW 32, clutch pipe delivery	23.02.2011	09:26	13,2	colorless, clear	0,46	0	0	0	0	0	0	0
110050678	Tank vehicle KWW 33, clutch pipe delivery	23.02.2011	09:18	11,1	colorless, clear	0,55	0	0	0	0	0	0	0
110050679	Tank vehicle KWW 34, clutch pipe delivery	23.02.2011	09:45	11,8	colorless, clear	0,54	0	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500287891
Report February 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2 °C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
110050680	Tank vehicle KWW 35, clutch pipe delivery	23.02.2011	09:35	7,2	colorless, clear	0,45	0	0	0	0	0
110050681	Tank vehicle KWW 36, clutch pipe delivery	23.02.2011	09:30	12,7	colorless, clear	0,53	0	0	0	0	0
110050682	Tank vehicle KWW 37, clutch pipe delivery	23.02.2011	09:43	11,2	colorless, clear	0,55	0	1	0	0	0
110050683	Tank vehicle KWW 38, clutch pipe delivery	23.02.2011	09:13	11,7	colorless, clear	0,54	0	0	0	0	0
110050684	Tank vehicle KWW 39, clutch pipe delivery	23.02.2011	09:10	11,1	colorless, clear	0,50	0	0	0	0	0
110050685	Tank vehicle KWW 40, clutch pipe delivery	23.02.2011	09:33	8,4	colorless, clear	0,51	0	0	0	0	0
110050686	Tank vehicle KWW 41, clutch pipe delivery	23.02.2011	09:38	8,2	colorless, clear	0,43	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, march 03, 2011
