

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report July 2011**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
110395086	Drinking water Delivery Tap 1	27.07.2011	10:10	17,5	colorless, clear	0,59	0	0	0	0	0
110395087	Drinking water Delivery Tap 2	27.07.2011	10:07	17,5	colorless, clear	0,64	1	0	0	0	0
110395088	Drinking water Delivery Tap 3	27.07.2011	10:04	17,5	colorless, clear	0,44	0	0	0	0	0
110395089	Drinking water Delivery Tap 4	27.07.2011	10:02	17,5	colorless, clear	0,39	0	0	0	0	0
110395090	Tank vehicle KWW 28, clutch pipe delivery	27.07.2011	09:52	19,4	colorless, clear	0,16	0	0	0	0	0
110395206	Tank vehicle KWW 29, clutch pipe delivery	27.07.2011	10:16	18,4	colorless, clear	0,52	0	0	0	0	0
110395208	Tank vehicle KWW 31, clutch pipe delivery	27.07.2011	09:30	19,9	colorless, clear	0,49	0	0	0	0	0
110395209	Tank vehicle KWW 32, clutch pipe delivery	27.07.2011	09:55	19,0	colorless, clear	0,21	0	0	0	0	> 100
110395210	Tank vehicle KWW 33, clutch pipe delivery	27.07.2011	09:27	18,6	colorless, clear	0,60	0	0	0	0	0
110395211	Tank vehicle KWW 34, clutch pipe delivery	27.07.2011	09:32	19,8	colorless, clear	0,39	0	0	0	0	0
110395212	Tank vehicle KWW 35, clutch pipe delivery	27.07.2011	09:40	18,6	colorless, clear	0,55	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report July 2011**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
110395213	Tank vehicle KWW 36, clutch pipe delivery	27.07.2011	09:25	18,2	colorless, clear	0,63	0	0	0	0	0
110395214	Tank vehicle KWW 37, clutch pipe delivery	27.07.2011	09:47	19,0	colorless, clear	0,51	0	0	0	0	0
110395215	Tank vehicle KWW 38, clutch pipe delivery	27.07.2011	09:22	19,1	colorless, clear	0,50	0	0	0	0	0
110395216	Tank vehicle KWW 39, clutch pipe delivery	27.07.2011	09:59	19,4	colorless, clear	0,48	0	0	0	0	0
110395217	Tank vehicle KWW 40, clutch pipe delivery	27.07.2011	09:45	18,4	colorless, clear	0,56	0	0	0	0	0
110395218	Tank vehicle KWW 41, clutch pipe delivery	27.07.2011	09:34	19,9	colorless, clear	0,49	0	0	0	0	5

**Assessment:**

According to the investigations of the German Drinking Water Regulation the following parameter of the testing samples **110395209** and **110395218** out of limit value: **Pseudomonas aeruginosa**

The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

**SGS INSTITUT FRESENIUS GmbH**

Taunusstein, august 05, 2011

\_\_\_\_\_