

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report May 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C		DEV agar after 44 ± 4 h at 36 ± 2°C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110245425	Drinking water Delivery Tap 1	03.05.2011	10:45	14,4	colorless, clear	0,82	0	0	0	0	0	0	0
110245427	Drinking water Delivery Tap 2	03.05.2011	10:48	14,6	colorless, clear	0,85	0	0	0	0	0	0	0
110245428	Drinking water Delivery Tap 3	03.05.2011	10:50	14,4	colorless, clear	0,85	0	0	0	0	0	0	0
110245429	Drinking water Delivery Tap 4	03.05.2011	10:55	14,6	colorless, clear	0,93	0	0	0	0	0	0	0
110245430	Tank vehicle KWW 28, clutch pipe delivery	03.05.2011	10:20	14,6	colorless, clear	0,72	0	0	0	0	0	0	0
110245431	Tank vehicle KWW 29, clutch pipe delivery	03.05.2011	10:22	14,6	colorless, clear	1,19	0	0	0	0	0	0	0
110245443	Tank vehicle KWW 30, clutch pipe delivery	03.05.2011	09:58	14,5	colorless, clear	< 0,03	0	0	0	0	0	0	0
110245444	Tank vehicle KWW 31, clutch pipe delivery	03.05.2011	10:27	14,1	colorless, clear	0,12	0	0	0	0	0	0	0
110245445	Tank vehicle KWW 32, clutch pipe delivery	03.05.2011	10:32	14,4	colorless, clear	0,04	0	0	0	0	0	0	35
110245447	Tank vehicle KWW 34, clutch pipe delivery	03.05.2011	10:05	14,9	colorless, clear	0,83	0	0	0	0	0	0	0
110245448	Tank vehicle KWW 35, clutch pipe delivery	03.05.2011	10:03	14,3	colorless, clear	< 0,03	0	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report May 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C		DEV agar after 44 ± 4 h at 36 ± 2 °C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110245449	Tank vehicle KWW 36, clutch pipe delivery	03.05.2011	10:12	14,7	colorless, clear	< 0,03	0		0		0	0	0
110245450	Tank vehicle KWW 37, clutch pipe delivery	03.05.2011	09:52	15,0	colorless, clear	1,37	0		0		0	0	0
110245451	Tank vehicle KWW 38, clutch pipe delivery	03.05.2011	10:00	14,2	colorless, clear	0,38	0		0		0	0	0
110245452	Tank vehicle KWW 39, clutch pipe delivery	03.05.2011	09:54	14,7	colorless, clear	0,49	0		0		0	0	0
110245453	Tank vehicle KWW 40, clutch pipe delivery	03.05.2011	10:07	14,4	colorless, clear	0,88	0		0		0	0	0
110245454	Tank vehicle KWW 41, clutch pipe delivery	03.05.2011	10:30	14,8	colorless, clear	1,56	0		0		0	0	0

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample **110245445** out of limit value: **Pseudomonas aeruginosa**
 The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, may 20, 2011
