

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report September 2011**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C		DEV agar after 44 ± 4 h at 36 ± 2°C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110617319	Drinking water Delivery Tap 1	26.10.2011	10:10	16,1	colorless, clear	0,94	0		0		0	0	0
110617320	Drinking water Delivery Tap 2	26.10.2011	10:01	16,8	colorless, clear	0,98	0		0		0	0	0
110617321	Drinking water Delivery Tap 3	26.10.2011	09:59	15,7	colorless, clear	0,48	0		1		0	0	0
110617322	Drinking water Delivery Tap 4	26.10.2011	09:55	16,1	colorless, clear	0,94	0		0		0	0	0
110617323	Tank vehicle KWW 28, clutch pipe delivery	26.10.2011	09:39	15,2	colorless, clear	0,42	0		1		0	0	0
110617324	Tank vehicle KWW 29, clutch pipe delivery	26.10.2011	09:41	14,7	colorless, clear	0,57	0		0		0	0	0
110617325	Tank vehicle KWW 30, clutch pipe delivery	26.10.2011	09:51	15,6	colorless, clear	0,65	0		0		0	0	0
110617326	Tank vehicle KWW 31, clutch pipe delivery	26.10.2011	10:15	16,0	colorless, clear	0,50	0		0		0	0	0
110617327	Tank vehicle KWW 32, clutch pipe delivery	26.10.2011	09:33	15,9	colorless, clear	0,82	0		0		0	0	0
110617328	Tank vehicle KWW 33, clutch pipe delivery	26.10.2011	09:20	15,9	colorless, clear	0,78	0		0		0	0	0
110617329	Tank vehicle KWW 34, clutch pipe delivery	26.10.2011	09:36	15,3	colorless, clear	0,63	0		0		0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report September 2011**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C		DEV agar after 44 ± 4 h at 36 ± 2 °C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110617332	Tank vehicle KWW 37, clutch pipe delivery	26.10.2011	09:15	16,4	colorless, clear	0,73	0		0		0	0	0
110617157	Tank vehicle KWW 38, clutch pipe delivery	26.10.2011	09:43	14,9	colorless, clear	0,53	0		0		0	0	0
110617158	Tank vehicle KWW 39, clutch pipe delivery	26.10.2011	09:23	15,9	colorless, clear	0,70	0		0		0	0	0
110617159	Tank vehicle KWW 40, clutch pipe delivery	26.10.2011	09:25	15,4	colorless, clear	0,52	0		0		0	0	0
110617160	Tank vehicle KWW 41, clutch pipe delivery	26.10.2011	09:46	16,1	colorless, clear	0,82	0		0		0	0	0

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

**SGS INSTITUT FRESENIUS GmbH**

Taunusstein, November 02, 2011

\_\_\_\_\_