

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report September 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C		DEV agar after 44 ± 4 h at 36 ± 2°C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110546550	Drinking water Delivery Tap 1	05.09.2011	09:27	18,0	colorless, clear	0,48	0		0		0	0	0
110546651	Drinking water Delivery Tap 2	05.09.2011	09:30	17,7	colorless, clear	0,52	0		0		0	0	0
110546652	Drinking water Delivery Tap 3	05.09.2011	09:35	17,7	colorless, clear	0,28	0		0		0	0	0
110546653	Drinking water Delivery Tap 4	05.09.2011	09:40	17,7	colorless, clear	0,41	0		0		0	0	0
110546654	Tank vehicle KWW 28, clutch pipe delivery	05.09.2011	09:16	20,3	colorless, clear	0,12	0		0		0	0	0
110546656	Tank vehicle KWW 30, clutch pipe delivery	05.09.2011	09:07	18,7	colorless, clear	0,37	0		0		0	0	0
110546658	Tank vehicle KWW 32, clutch pipe delivery	05.09.2011	09:00	19,5	colorless, clear	0,37	0		0		0	0	1
110546659	Tank vehicle KWW 33, clutch pipe delivery	05.09.2011	09:05	19,6	colorless, clear	0,17	0		55		0	0	0
110546661	Tank vehicle KWW 35, clutch pipe delivery	05.09.2011	09:37	18,4	colorless, clear	0,42	0		0		0	0	0
110546662	Tank vehicle KWW 36, clutch pipe delivery	05.09.2011	09:32	20,2	colorless, clear	0,12	0		0		0	0	0
110546663	Tank vehicle KWW 37, clutch pipe delivery	05.09.2011	09:24	18,7	colorless, clear	0,39	0		0		0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report September 2011

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C		DEV agar after 44 ± 4 h at 36 ± 2 °C		Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
							KBE/ml	Limit Value 100	KBE/ml	Limit Value 100			
110546666	Tank vehicle KWW 38, clutch pipe delivery	05.09.2011	09:42	18,7	colorless, clear	0,39	0		0		0	0	0
110546667	Tank vehicle KWW 39, clutch pipe delivery	05.09.2011	09:13	20,0	colorless, clear	0,16	0		0		0	0	4
110545693	Tank vehicle KWW 40, clutch pipe delivery	05.09.2011	08:54	20,8	colorless, clear	0,21	0		0		0	0	0
110545694	Tank vehicle KWW 41, clutch pipe delivery	05.09.2011	08:58	18,4	colorless, clear	0,49	0		0		0	0	1

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing samples **110546658, 110546667 and 110545694** out of limit value: **Pseudomonas aeruginosa**

The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, September 13, 2011
