

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report February 2012

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
120054272	Drinking water Delivery Tap 1	24.02.2012	09:15	12,4	colorless, clear	1,00	0	0	0	0	0
120054288	Drinking water Delivery Tap 2	24.02.2012	09:22	12,0	colorless, clear	0,40	0	0	0	0	0
120054290	Drinking water Delivery Tap 3	24.02.2012	09:24	12,4	colorless, clear	0,46	0	0	0	0	0
120054291	Drinking water Delivery Tap 4	24.02.2012	09:28	11,6	colorless, clear	0,70	0	0	0	0	0
120054292	Tank vehicle KWW 28, clutch pipe delivery	24.02.2012	10:02	10,4	colorless, clear	0,36	0	0	0	0	0
120054293	Tank vehicle KWW 29, clutch pipe delivery	24.02.2012	09:40	12,6	colorless, clear	0,46	0	0	0	0	0
120054294	Tank vehicle KWW 30, clutch pipe delivery	24.02.2012	09:34	11,4	colorless, clear	0,32	0	0	0	0	0
120054375	Tank vehicle KWW 32, clutch pipe delivery	24.02.2012	10:06	11,8	colorless, clear	0,40	0	0	0	0	0
120054376	Tank vehicle KWW 33, clutch pipe delivery	28.02.2012	11:45	11,6	colorless, clear	0,39	0	0	0	0	0
120054377	Tank vehicle KWW 34, clutch pipe delivery	24.02.2012	09:58	11,6	colorless, clear	0,50	0	0	0	0	0
120054378	Tank vehicle KWW 35, clutch pipe delivery	24.02.2012	09:50	12,0	colorless, clear	0,48	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report February 2012

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
120054379	Tank vehicle KWW 36, clutch pipe delivery	24.02.2012	09:46	12,0	colorless, clear	0,40	0	0	0	0	0
120054380	Tank vehicle KWW 37, clutch pipe delivery	24.02.2012	09:52	12,4	colorless, clear	0,40	0	0	0	0	0
120054381	Tank vehicle KWW 38, clutch pipe delivery	24.02.2012	09:50	12,0	colorless, clear	0,50	0	0	0	0	0
120054382	Tank vehicle KWW 39, clutch pipe delivery	24.02.2012	09:45	12,0	colorless, clear	0,60	0	0	0	0	0
120054383	Tank vehicle KWW 40, clutch pipe delivery	24.02.2012	10:00	11,6	colorless, clear	0,44	0	0	0	0	0
120054384	Tank vehicle KWW 41, clutch pipe delivery	24.02.2012	09:42	12,0	colorless, clear	0,50	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, March 02, 2012
