

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report January 2012

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
110843382	Drinking water Delivery Tap 1	18.01.2012	10:33	13,2	colorless, clear	0,59	0	0	0	0	0
110843383	Drinking water Delivery Tap 2	18.01.2012	10:36	14,2	colorless, clear	0,61	0	0	0	0	0
110843389	Drinking water Delivery Tap 3	18.01.2012	10:45	12,7	colorless, clear	0,35	0	0	0	0	0
110843390	Drinking water Delivery Tap 4	18.01.2012	09:55	13,0	colorless, clear	0,82	0	0	0	0	0
110843391	Tank vehicle KWW 28, clutch pipe delivery	18.01.2012	10:15	12,8	colorless, clear	0,56	0	0	0	0	0
110843392	Tank vehicle KWW 29, clutch pipe delivery	18.01.2012	09:35	8,4	colorless, clear	0,54	0	0	0	0	0
110843393	Tank vehicle KWW 30, clutch pipe delivery	18.01.2012	09:47	7,8	colorless, clear	0,53	0	0	0	0	0
110843394	Tank vehicle KWW 31, clutch pipe delivery	18.01.2012	10:00	12,4	colorless, clear	0,47	0	0	0	0	0
110843395	Tank vehicle KWW 32, clutch pipe delivery	18.01.2012	10:06	11,9	colorless, clear	0,36	0	0	0	0	0
110843396	Tank vehicle KWW 33, clutch pipe delivery	18.01.2012	10:20	12,4	colorless, clear	0,59	0	0	0	0	0
110843397	Tank vehicle KWW 34, clutch pipe delivery	18.01.2012	09:36	10,2	colorless, clear	0,44	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report January 2012

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2 °C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
110843398	Tank vehicle KWW 35, clutch pipe delivery	18.01.2012	09:50	5,2	colorless, clear	0,50	0	0	0	0	0
110843399	Tank vehicle KWW 36, clutch pipe delivery	18.01.2012	10:34	13,2	colorless, clear	0,48	0	0	0	0	0
110843400	Tank vehicle KWW 37, clutch pipe delivery	18.01.2012	09:32	12,0	colorless, clear	0,53	0	0	0	0	0
110843401	Tank vehicle KWW 38, clutch pipe delivery	18.01.2012	10:03	7,1	colorless, clear	0,46	0	0	0	0	0
110843402	Tank vehicle KWW 39, clutch pipe delivery	18.01.2012	09:40	12,5	colorless, clear	0,71	0	0	0	0	0
110843403	Tank vehicle KWW 40, clutch pipe delivery	18.01.2012	09:52	12,1	colorless, clear	0,60	0	0	0	0	0
110843404	Tank vehicle KWW 41, clutch pipe delivery	18.01.2012	10:10	8,6	colorless, clear	0,33	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, January 24, 2012
