

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report July 2012**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
120436920	Drinking water Delivery Tap 1	06.07.2012	09:44	19,4	colorless, clear	0,77	0	1	0	0	0
120436924	Drinking water Delivery Tap 2	06.07.2012	09:49	22,7	colorless, clear	0,90	0	0	0	0	0
120436925	Drinking water Delivery Tap 3	06.07.2012	09:51	19,4	colorless, clear	1,36	0	3	0	0	0
120436926	Drinking water Delivery Tap 4	06.07.2012	10:00	19,2	colorless, clear	0,22	0	4	0	0	0
120436927	Tank vehicle KWW 28, clutch pipe delivery	06.07.2012	09:32	21,3	colorless, clear	0,95	0	0	0	0	0
120436928	Tank vehicle KWW 29, clutch pipe delivery	06.07.2012	09:34	22,4	colorless, clear	0,65	0	1	0	0	0
120436929	Tank vehicle KWW 30, clutch pipe delivery	06.07.2012	09:10	20,5	colorless, clear	0,75	0	0	0	0	0
120436930	Tank vehicle KWW 31, clutch pipe delivery	06.07.2012	09:13	20,3	colorless, clear	0,75	0	0	0	0	0
120436931	Tank vehicle KWW 32, clutch pipe delivery	06.07.2012	09:23	22,3	colorless, clear	0,62	0	0	0	0	0
120436932	Tank vehicle KWW 33, clutch pipe delivery	06.07.2012	09:29	19,9	colorless, clear	0,90	0	0	0	0	0
120436933	Tank vehicle KWW 34, clutch pipe delivery	06.07.2012	09:18	22,3	colorless, clear	0,60	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report July 2012**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2 °C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
120436934	Tank vehicle KWW 35, clutch pipe delivery	06.07.2012	09:46	20,5	colorless, clear	0,70	1	1	0	0	0
120436935	Tank vehicle KWW 36, clutch pipe delivery	06.07.2012	09:26	23,3	colorless, clear	0,72	0	0	0	0	0
120436936	Tank vehicle KWW 37, clutch pipe delivery	06.07.2012	10:02	20,6	colorless, clear	0,67	0	0	0	0	0
120436937	Tank vehicle KWW 38, clutch pipe delivery	06.07.2012	09:20	20,3	colorless, clear	0,97	0	1	0	0	0
120436938	Tank vehicle KWW 39, clutch pipe delivery	06.07.2012	09:36	22,7	colorless, clear	0,63	0	1	0	0	0
120436939	Tank vehicle KWW 40, clutch pipe delivery	06.07.2012	09:15	19,7	colorless, clear	0,99	0	4	0	0	0
120436940	Tank vehicle KWW 41, clutch pipe delivery	06.07.2012	09:40	20,1	colorless, clear	0,83	0	0	0	0	0

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

**SGS INSTITUT FRESENIUS GmbH**

Taunusstein, July 10, 2012

\_\_\_\_\_