

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report June 2012**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
120365132	Drinking water Delivery Tap 1	27.06.2012	10:50	18,4	colorless, clear	0,91	0	0	0	0	0
120365134	Drinking water Delivery Tap 2	27.06.2012	10:57	23,4	colorless, clear	0,71	0	0	0	0	0
120365135	Drinking water Delivery Tap 3	27.06.2012	10:56	18,4	colorless, clear	0,42	0	0	0	0	0
120365136	Drinking water Delivery Tap 4	27.06.2012	11:00	19,0	colorless, clear	1,38	0	0	0	0	0
120365137	Tank vehicle KWW 28, clutch pipe delivery	27.06.2012	10:37	18,6	colorless, clear	0,84	0	0	0	0	0
120365138	Tank vehicle KWW 29, clutch pipe delivery	27.06.2012	10:16	19,7	colorless, clear	0,76	0	0	0	0	0
120365139	Tank vehicle KWW 30, clutch pipe delivery	27.06.2012	10:36	18,8	colorless, clear	0,88	0	0	0	0	0
120365140	Tank vehicle KWW 31, clutch pipe delivery	27.06.2012	10:28	19,5	colorless, clear	0,75	0	0	0	0	0
120365141	Tank vehicle KWW 32, clutch pipe delivery	27.06.2012	10:19	21,1	colorless, clear	0,78	0	0	0	0	0
120365142	Tank vehicle KWW 33, clutch pipe delivery	27.06.2012	10:21	20,4	colorless, clear	0,79	0	0	0	0	0
120365143	Tank vehicle KWW 34, clutch pipe delivery	27.06.2012	10:45	20,4	colorless, clear	0,68	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580**  
**Report June 2012**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2 °C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2 °C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0
120365144	Tank vehicle KWW 35, clutch pipe delivery	27.06.2012	10:13	18,6	colorless, clear	1,03	0	0	0	0	0
120365145	Tank vehicle KWW 36, clutch pipe delivery	27.06.2012	10:25	20,0	colorless, clear	0,95	0	0	0	0	0
120365147	Tank vehicle KWW 37, clutch pipe delivery	27.06.2012	10:29	18,8	colorless, clear	0,87	0	0	0	0	0
120365148	Tank vehicle KWW 38, clutch pipe delivery	27.06.2012	11:10	19,5	colorless, clear	0,66	0	0	0	0	0
120365183	Tank vehicle KWW 39, clutch pipe delivery	27.06.2012	10:10	21,6	colorless, clear	0,58	0	0	0	0	0
120365184	Tank vehicle KWW 40, clutch pipe delivery	27.06.2012	10:32	20,0	colorless, clear	1,18	0	0	0	0	0
120365185	Tank vehicle KWW 41, clutch pipe delivery	27.06.2012	10:07	21,0	colorless, clear	0,75	0	0	0	0	1

**Assessment:**

According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample **120365185** out of limit value: **Pseudomonas aeruginosa**  
 The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, July 10, 2012