

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report November 2012

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
120812641	Drinking water Delivery Tap 1	06.11.2012	10:33	15,4	colorless, clear	0,71	0	0	0	0	0	0
120812642	Drinking water Delivery Tap 2	06.11.2012	10:36	18,4	colorless, clear	0,41	0	0	0	0	0	0
120812643	Drinking water Delivery Tap 3	06.11.2012	10:40	15,4	colorless, clear	0,30	0	0	0	0	0	0
120812644	Drinking water Delivery Tap 4	06.11.2012	09:44	16,1	colorless, clear	0,50	0	0	0	0	0	0
120812645	Tank vehicle KWW 28, clutch pipe delivery	06.11.2012	10:13	14,2	colorless, clear	0,75	0	0	0	0	0	0
120812646	Tank vehicle KWW 29, clutch pipe delivery	06.11.2012	09:52	13,2	colorless, clear	0,55	0	0	0	0	0	0
120812647	Tank vehicle KWW 30, clutch pipe delivery	06.11.2012	09:55	11,5	colorless, clear	0,46	0	0	0	0	0	0
120812648	Tank vehicle KWW 31, clutch pipe delivery	06.11.2012	10:16	16,1	colorless, clear	0,72	0	0	0	0	0	0
120812649	Tank vehicle KWW 32, clutch pipe delivery	06.11.2012	09:58	13,5	colorless, clear	0,54	0	0	0	0	0	0
120812650	Tank vehicle KWW 33, clutch pipe delivery	06.11.2012	10:05	15,1	colorless, clear	0,80	0	0	0	0	0	0
120812701	Tank vehicle KWW 34, clutch pipe delivery	06.11.2012	10:21	12,1	colorless, clear	0,60	0	0	0	0	0	0
120812702	Tank vehicle KWW 35, clutch pipe delivery	06.11.2012	10:01	14,1	colorless, clear	0,77	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500319580
Report November 2012**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
120812703	Tank vehicle KWW 36, clutch pipe delivery	06.11.2012	10:26	12,1	colorless, clear	0,38	0	0	0	0	0	0
120812704	Tank vehicle KWW 37, clutch pipe delivery	06.11.2012	09:47	13,7	colorless, clear	0,68	0	2	0	0	0	0
120812705	Tank vehicle KWW 38, clutch pipe delivery	06.11.2012	09:43	15,4	colorless, clear	0,74	0	0	0	0	0	0
120812706	Tank vehicle KWW 39, clutch pipe delivery	06.11.2012	10:29	13,5	colorless, clear	0,67	0	0	0	0	0	0
120812707	Tank vehicle KWW 40, clutch pipe delivery	06.11.2012	09:45	15,2	colorless, clear	0,76	0	0	0	0	0	0
120812708	Tank vehicle KWW 41, clutch pipe delivery	06.11.2012	10:09	14,7	colorless, clear	0,72	0	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, November 13, 2012