

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500402775
Report July 2013**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
130542767	Drinking water Delivery Tap 1	30.07.2013	09:52	21,0	colorless, clear	0,91	0	0	0	0	0	0
130542768	Drinking water Delivery Tap 2	30.07.2013	09:47	21,1	colorless, clear	0,90	0	0	0	0	0	0
130542769	Drinking water Delivery Tap 3	30.07.2013	09:43	22,3	colorless, clear	0,99	0	0	0	0	0	0
130542770	Drinking water Delivery Tap 4	30.07.2013	09:32	21,2	colorless, clear	1,10	0	0	0	0	0	0
130542772	Tank vehicle KWW 29, clutch pipe delivery	30.07.2013	09:20	21,4	colorless, clear	0,88	0	0	0	0	0	0
130542773	Tank vehicle KWW 30, clutch pipe delivery	30.07.2013	09:05	22,2	colorless, clear	2,12	0	0	0	0	0	0
130542779	Tank vehicle KWW 31, clutch pipe delivery	30.07.2013	09:27	21,0	colorless, clear	0,74	0	0	0	0	0	0
130542780	Tank vehicle KWW 32, clutch pipe delivery	30.07.2013	09:25	21,4	colorless, clear	0,93	0	0	0	0	0	0
130542781	Tank vehicle KWW 33, clutch pipe delivery	30.07.2013	09:10	21,1	colorless, clear	0,97	0	0	0	0	0	0
130542782	Tank vehicle KWW 34, clutch pipe delivery	30.07.2013	09:35	21,8	colorless, clear	0,88	0	0	0	0	0	0
130542798	Tank vehicle KWW 35, clutch pipe delivery	30.07.2013	09:12	21,8	colorless, clear	0,84	0	0	0	0	0	0
130542800	Tank vehicle KWW 37, clutch pipe delivery	30.07.2013	09:38	21,8	colorless, clear	0,84	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500402775
Report July 2013**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
130542901	Tank vehicle KWW 38, clutch pipe delivery	30.07.2013	09:07	22,1	colorless, clear	1,11	0	0	0	0	0	0
130542902	Tank vehicle KWW 39, clutch pipe delivery	30.07.2013	09:02	22,2	colorless, clear	0,90	0	0	0	0	0	0
130542903	Tank vehicle KWW 40, clutch pipe delivery	30.07.2013	09:15	22,0	colorless, clear	0,86	0	0	0	0	0	0
130542904	Tank vehicle KWW 41, clutch pipe delivery	30.07.2013	09:18	21,2	colorless, clear	1,02	0	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Tausenstein, August 09, 2013
