

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500403775
Report October 2013**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
130864061	Drinking water Delivery Tap 1	29.10.2013	10:04	17,1	colorless, clear	0,34	0	0	0	0	0	0
130864062	Drinking water Delivery Tap 2	29.10.2013	09:59	17,1	colorless, clear	0,70	0	0	0	0	0	0
130864063	Drinking water Delivery Tap 3	29.10.2013	09:40	17,1	colorless, clear	0,78	0	0	0	0	0	0
130864064	Drinking water Delivery Tap 4	29.10.2013	09:30	16,9	colorless, clear	0,73	0	0	0	0	0	0
130864065	Tank vehicle KWW 28, clutch pipe delivery	29.10.2013	09:18	16,6	colorless, clear	0,67	0	0	0	0	0	0
130864066	Tank vehicle KWW 29, clutch pipe delivery	29.10.2013	09:46	16,6	colorless, clear	0,48	1	0	0	0	0	0
130864067	Tank vehicle KWW 30, clutch pipe delivery	29.10.2013	09:21	17,1	colorless, clear	0,47	0	0	0	0	0	0
130864068	Tank vehicle KWW 31, clutch pipe delivery	29.10.2013	09:15	17,1	colorless, clear	0,47	3	0	0	0	0	0
130864069	Tank vehicle KWW 32, clutch pipe delivery	29.10.2013	09:48	16,6	colorless, clear	0,44	0	0	0	0	0	0
130864070	Tank vehicle KWW 33, clutch pipe delivery	29.10.2013	09:11	16,6	colorless, clear	0,56	0	0	0	0	0	0
130864071	Tank vehicle KWW 34, clutch pipe delivery	29.10.2013	09:43	16,1	colorless, clear	0,44	1	0	0	0	0	0
130864074	Tank vehicle KWW 37, clutch pipe delivery	29.10.2013	10:15	16,1	colorless, clear	0,52	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500403775
Report October 2013**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
130864075	Tank vehicle KWW 38, clutch pipe delivery	29.10.2013	09:36	15,5	colorless, clear	0,44	0	0	0	0	0	0
130864076	Tank vehicle KWW 39, clutch pipe delivery	29.10.2013	09:54	16,4	colorless, clear	0,58	0	1	0	0	0	0
130864077	Tank vehicle KWW 40, clutch pipe delivery	29.10.2013	09:51	16,6	colorless, clear	0,58	0	0	0	0	0	0
130864078	Tank vehicle KWW 41, clutch pipe delivery	29.10.2013	09:25	17,1	colorless, clear	0,66	0	0	0	0	0	0

Assessment:

The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, November 06, 2013
