

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981
Report August 2014**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
140952651	Drinking water Delivery Tap 1	29.08.2014	11:30	17,4	colorless, clear	0,80	0	0	0	0	5	0
140952652	Drinking water Delivery Tap 2	29.08.2014	11:28	16,8	colorless, clear	0,40	0	0	0	0	0	0
140952653	Drinking water Delivery Tap 3	29.08.2014	11:25	17,4	colorless, clear	0,80	0	0	0	0	0	0
140952654	Drinking water Delivery Tap 4	29.08.2014	11:20	16,6	colorless, clear	0,60	0	0	0	0	0	0
140952655	Tank vehicle KWW 30, clutch pipe delivery	29.08.2014	10:52	17,8	colorless, clear	0,90	0	4	0	0	0	0
140952656	Tank vehicle KWW 31, clutch pipe delivery	29.08.2014	10:20	19,2	colorless, clear	1,00	0	0	0	0	0	0
140952657	Tank vehicle KWW 32, clutch pipe delivery	29.08.2014	10:30	19,2	colorless, clear	0,80	0	0	0	0	0	0
140952658	Tank vehicle KWW 33, clutch pipe delivery	29.08.2014	10:25	19,4	colorless, clear	1,00	0	3	0	0	0	0
140952659	Tank vehicle KWW 34, clutch pipe delivery	29.08.2014	10:55	17,4	colorless, clear	1,30	0	0	0	0	0	0
140952660	Tank vehicle KWW 35, clutch pipe delivery	29.08.2014	11:05	20,0	colorless, clear	1,00	0	0	0	0	0	0
140952661	Tank vehicle KWW 36, clutch pipe delivery	29.08.2014	10:45	18,0	colorless, clear	0,70	0	0	0	0	0	0
140952664	Tank vehicle KWW 39, clutch pipe delivery	29.08.2014	11:15	20,4	colorless, clear	0,90	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981
Report August 2014**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
140952665	Tank vehicle KWW 40, clutch pipe delivery	29.08.2014	10:35	18,4	colorless, clear	0,90	0	0	0	0	0	0
140952666	Tank vehicle KWW 41, clutch pipe delivery	29.08.2014	10:32	18,8	colorless, clear	1,10	0	0	0	0	0	0
140952667	Tank vehicle KWW 42, clutch pipe delivery	29.08.2014	11:10	20,0	colorless, clear	1,10	0	1	0	0	0	0
140952668	Tank vehicle KWW 43, clutch pipe delivery	29.08.2014	10:40	18,0	colorless, clear	0,80	0	0	0	0	0	0

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample 140952651 out of limit value: **Pseudomonas aeruginosa**

The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, September 02, 2014