

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981  
Report February 2014**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
131240155	Drinking water Delivery Tap 1	26.02.2014	09:54	13,2	colorless, clear	0,94	0	0	0	0	0	0
131240156	Drinking water Delivery Tap 2	26.02.2014	10:00	12,7	colorless, clear	0,71	0	0	0	0	0	0
131240157	Drinking water Delivery Tap 3	26.02.2014	10:10	13,7	colorless, clear	0,35	0	0	0	0	0	0
131240158	Drinking water Delivery Tap 4	26.02.2014	10:20	13,4	colorless, clear	0,89	0	0	0	0	0	0
131240164	Tank vehicle KWW 30, clutch pipe delivery	26.02.2014	09:43	10,8	colorless, clear	1,13	0	0	0	0	0	0
131240185	Tank vehicle KWW 31, clutch pipe delivery	26.02.2014	09:46	12,7	colorless, clear	0,92	0	0	0	0	0	0
131240186	Tank vehicle KWW 32, clutch pipe delivery	26.02.2014	09:24	12,7	colorless, clear	1,04	0	0	0	0	0	0
131240187	Tank vehicle KWW 33, clutch pipe delivery	26.02.2014	09:38	12,5	colorless, clear	0,89	0	0	0	0	0	0
131240189	Tank vehicle KWW 34, clutch pipe delivery	26.02.2014	09:30	12,6	colorless, clear	0,90	0	0	0	0	0	0
131240190	Tank vehicle KWW 36, clutch pipe delivery	26.02.2014	09:26	12,6	colorless, clear	0,88	0	0	0	0	0	0
131240191	Tank vehicle KWW 37, clutch pipe delivery	26.02.2014	09:28	12,7	colorless, clear	1,02	0	0	0	0	0	0
131240192	Tank vehicle KWW 38, clutch pipe delivery	26.02.2014	09:35	12,0	colorless, clear	0,98	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981  
Report February 2014**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
131240193	Tank vehicle KWW 39, clutch pipe delivery	26.02.2014	10:02	11,8	colorless, clear	0,89	0	0	0	0	0	0
131240194	Tank vehicle KWW 40, clutch pipe delivery	26.02.2014	09:40	12,4	colorless, clear	1,00	0	0	0	0	0	0
131240198	Tank vehicle KWW 41, clutch pipe delivery	26.02.2014	09:33	12,5	colorless, clear	0,86	0	0	0	0	0	0
131240199	Tank vehicle KWW 41, clutch pipe delivery	26.02.2014	09:22	12,7	colorless, clear	1,01	0	0	0	0	0	0
131240200	Tank vehicle KWW 43, clutch pipe delivery	26.02.2014	09:48	12,2	colorless, clear	0,93	0	0	0	0	0	0

**Assessment:**

The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

**SGS INSTITUT FRESENIUS GmbH**

Taunusstein, March 03, 2014 \_\_\_\_\_