

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981
Report July 2014**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
140718576	Drinking water Delivery Tap 1	09.07.2014	10:30	19,5	colorless, clear	0,55	0	0	0	0	0	0
140718577	Drinking water Delivery Tap 2	09.07.2014	10:17	19,2	colorless, clear	0,64	0	0	0	0	0	0
140718578	Drinking water Delivery Tap 3	09.07.2014	10:22	19,9	colorless, clear	0,79	0	0	0	0	0	0
140718579	Drinking water Delivery Tap 4	09.07.2014	10:25	19,4	colorless, clear	1,06	0	0	0	0	0	0
140718580	Tank vehicle KWW 30, clutch pipe delivery	09.07.2014	09:47	19,4	colorless, clear	0,64	0	0	0	0	0	0
140718582	Tank vehicle KWW 32, clutch pipe delivery	09.07.2014	10:02	15,7	colorless, clear	0,48	0	0	0	0	0	0
140718583	Tank vehicle KWW 33, clutch pipe delivery	09.07.2014	09:32	15,3	colorless, clear	0,57	0	0	0	0	1	0
140718584	Tank vehicle KWW 34, clutch pipe delivery	09.07.2014	08:53	16,0	colorless, clear	0,52	0	0	0	0	0	0
140718585	Tank vehicle KWW 35, clutch pipe delivery	09.07.2014	10:06	15,3	colorless, clear	0,38	0	0	0	0	0	0
140718587	Tank vehicle KWW 37, clutch pipe delivery	09.07.2014	09:37	17,9	colorless, clear	0,33	0	0	0	0	0	0
140718591	Tank vehicle KWW 38, clutch pipe delivery	09.07.2014	09:35	17,2	colorless, clear	0,47	0	0	0	0	0	0
140718592	Tank vehicle KWW 39, clutch pipe delivery	09.07.2014	09:22	17,6	colorless, clear	0,72	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981
Report July 2014**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
140718593	Tank vehicle KWW 40, clutch pipe delivery	09.07.2014	09:40	15,1	colorless, clear	0,52	0	0	0	0	0	0
140718594	Tank vehicle KWW 41, clutch pipe delivery	09.07.2014	09:27	16,6	colorless, clear	0,47	0	0	0	0	0	0
140718595	Tank vehicle KWW 42, clutch pipe delivery	09.07.2014	09:24	18,6	colorless, clear	0,60	0	0	0	0	0	0
140718596	Tank vehicle KWW 43, clutch pipe delivery	09.07.2014	09:59	16,6	colorless, clear	0,53	0	0	0	0	0	0

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample 140718583 out of limit value: **Pseudomonas aeruginosa**

The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, July 16, 2014