

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981
Report January 2015**

| Sample ID | Sample designation | Sampling day | Sampling time | Water temperature °C | Description | Free chlorine mg/l | DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100 | DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100 | Escherichia coli KBE/100 ml Limit Value 0 | Coliforms KBE/100 ml Limit Value 0 | Pseudomonas aeruginosa KBE/100 ml Limit Value 0 | Enterococci KBE/100 ml Limit Value 0 |
|-----------|---|--------------|---------------|----------------------|------------------|--------------------|--|--|---|------------------------------------|---|--------------------------------------|
| 141379165 | Drinking water Delivery Tap 1 | 07.01.2015 | 09:05 | 11,6 | colorless, clear | 0,68 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379166 | Drinking water Delivery Tap 2 | 07.01.2015 | 09:30 | 12,0 | colorless, clear | 1,00 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379167 | Drinking water Delivery Tap 3 | 07.01.2015 | 09:35 | 11,8 | colorless, clear | 1,20 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379168 | Drinking water Delivery Tap 4 | 07.01.2015 | 09:40 | 11,3 | colorless, clear | 1,30 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379169 | Tank vehicle KWW 30, clutch pipe delivery | 07.01.2015 | 08:50 | 13,5 | colorless, clear | 0,68 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379170 | Tank vehicle KWW 31, clutch pipe delivery | 07.01.2015 | 08:55 | 9,2 | colorless, clear | 0,70 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379171 | Tank vehicle KWW 32, clutch pipe delivery | 07.01.2015 | 08:45 | 10,4 | colorless, clear | 0,58 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379172 | Tank vehicle KWW 33, clutch pipe delivery | 07.01.2015 | 08:30 | 11,6 | colorless, clear | 0,70 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379174 | Tank vehicle KWW 35, clutch pipe delivery | 07.01.2015 | 09:00 | 9,2 | colorless, clear | 0,72 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379175 | Tank vehicle KWW 36, clutch pipe delivery | 07.01.2015 | 09:20 | 10,0 | colorless, clear | 1,00 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379176 | Tank vehicle KWW 37, clutch pipe delivery | 07.01.2015 | 08:34 | 12,2 | colorless, clear | 0,70 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379177 | Tank vehicle KWW 38, clutch pipe delivery | 07.01.2015 | 09:10 | 10,0 | colorless, clear | 0,74 | 0 | 0 | 0 | 0 | 0 | 0 |

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981
Report January 2015**

| Sample ID | Sample designation | Sampling day | Sampling time | Water temperature °C | Description | Free chlorine mg/l | DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100 | DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100 | Escherichia coli KBE/100 ml Limit Value 0 | Coliforms KBE/100 ml Limit Value 0 | Pseudomonas aeruginosa KBE/100 ml Limit Value 0 | Enterococci KBE/100 ml Limit Value 0 |
|-----------|---|--------------|---------------|----------------------|------------------|--------------------|--|--|---|------------------------------------|---|--------------------------------------|
| 141379178 | Tank vehicle KWW 39, clutch pipe delivery | 07.01.2015 | 09:25 | 11,2 | colorless, clear | 0,64 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379180 | Tank vehicle KWW 40, clutch pipe delivery | 07.01.2015 | 08:50 | 11,5 | colorless, clear | 0,68 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379181 | Tank vehicle KWW 41, clutch pipe delivery | 07.01.2015 | 08:40 | 7,5 | colorless, clear | 0,70 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379182 | Tank vehicle KWW 42, clutch pipe delivery | 07.01.2015 | 09:15 | 7,8 | colorless, clear | 0,78 | 0 | 0 | 0 | 0 | 0 | 0 |
| 141379183 | Tank vehicle KWW 43, clutch pipe delivery | 07.01.2015 | 08:35 | 10,4 | colorless, clear | 0,70 | 0 | 0 | 0 | 0 | 0 | 0 |

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, January 14, 2015 _____