

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981
Report November 2015**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
150991627	Drinking water Delivery Tap 1	26.11.2015	09:50	16,1	colorless, clear	1,30	0	0	0	0	2	0
150991628	Drinking water Delivery Tap 2	26.11.2015	09:55	16,1	colorless, clear	1,47	0	0	0	0	0	0
150991629	Drinking water Delivery Tap 3	26.11.2015	10:00	16,1	colorless, clear	1,51	0	0	0	0	0	0
150991630	Drinking water Delivery Tap 4	26.11.2015	10:10	16,4	colorless, clear	1,63	0	0	0	0	0	0
150991631	Tank vehicle KWW 31, clutch pipe delivery	26.11.2015	09:00	7,5	colorless, clear	0,29	0	0	0	0	0	0
150991632	Tank vehicle KWW 32, clutch pipe delivery	26.11.2015	09:15	14,2	colorless, clear	1,26	0	0	0	0	0	0
150991633	Tank vehicle KWW 33, clutch pipe delivery	26.11.2015	09:05	14,3	colorless, clear	1,07	10	0	0	0	0	0
150991634	Tank vehicle KWW 34, clutch pipe delivery	26.11.2015	09:40	12,9	colorless, clear	1,26	0	0	0	0	0	0
150991635	Tank vehicle KWW 35, clutch pipe delivery	26.11.2015	10:05	10,4	colorless, clear	1,22	0	0	0	0	0	0
150991636	Tank vehicle KWW 36, clutch pipe delivery	26.11.2015	09:35	15,3	colorless, clear	1,32	0	0	0	0	0	0
150991637	Tank vehicle KWW 37, clutch pipe delivery	26.11.2015	09:45	13,9	colorless, clear	1,15	0	0	0	0	0	0
150991638	Tank vehicle KWW 38, clutch pipe delivery	26.11.2015	08:50	13,4	colorless, clear	1,22	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500438981
Report November 2015**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
150991639	Tank vehicle KWW 39, clutch pipe delivery	26.11.2015	09:50	10,6	colorless, clear	1,06	0	0	0	0	0	0
150991640	Tank vehicle KWW 40, clutch pipe delivery	26.11.2015	08:45	14,7	colorless, clear	0,74	0	0	0	0	0	0
150991641	Tank vehicle KWW 41, clutch pipe delivery	26.11.2015	08:55	10,4	colorless, clear	0,91	1	0	0	0	0	0
150991643	Tank vehicle KWW 43, clutch pipe delivery	26.11.2015	09:15	11,0	colorless, clear	1,09	0	0	0	0	0	0
150991644	Tank vehicle KWW 44, clutch pipe delivery	26.11.2015	09:20	14,4	colorless, clear	1,21	0	0	0	0	0	0

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample 150991627

is out of limit value: **Pseudomonas aeruginosa**

The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, December 01, 2015
