

Official drinking water examination conformable to the german drinking water regulations §§ 18 und 19 (TrinkwV 2001) from Mai 21st 2001 (BGBl. I p. 959) published on November 28th 2011 (BGBl. I p. 2370)

Fraport drinking water tank vehicles and delivery

Sampling date 23.03.2017

Mittwoch, 29. März 2017

Sample designation	Water temperature [°C]	pH-value ≥6,5 und ≤9,5	free chlorine [mg/l]	colony	colony	Escherichia	Coliforms	Pseudomonas	Enterococcus
				count at 22°C [KBE/ml] limit value 100	count at 36°C [KBE/ml] limit value 100	coli [KBE/100ml] limit value 0	[KBE/100ml] limit value 0	aeruginosa [KBE/100ml] limit value 0	[KBE/100ml] limit value 0
Tank vehicle KWW-32 clutch pipe delivery	11,5	7,8	0,77	0	0	0	0	0	0
Tank vehicle KWW-33 clutch pipe delivery	13,3	8,0	0,50	0	1	0	0	0	0
Tank vehicle KWW-34 clutch pipe delivery	10,6	8,0	0,51	0	1	0	0	0	0
Tank vehicle KWW-35 clutch pipe delivery	11,1	7,7	0,92	0	2	0	0	0	0
Tank vehicle KWW-36 clutch pipe delivery	12,5	7,9	0,40	0	1	0	0	0	0
Tank vehicle KWW-37 clutch pipe delivery	11,6	7,9	0,47	0	0	0	0	0	0
Tank vehicle KWW-38 clutch pipe delivery	10,7		0,07	0	2	0	0	0	0
Tank vehicle KWW-39 clutch pipe delivery	11,2	8,2	0,57	0	1	0	0	0	0
Tank vehicle KWW-40 clutch pipe delivery	11,4	7,9	0,75	0	0	0	0	0	0
Tank vehicle KWW-41 clutch pipe delivery	11,6	7,9	0,63	1	1	0	0	0	0
Tank vehicle KWW-42 clutch pipe delivery	10,8	8,0	0,54	0	0	0	0	0	0
Tank vehicle KWW-43 clutch pipe delivery	11,1	7,9	0,57	0	0	0	0	0	0
Tank vehicle KWW-44 clutch pipe delivery	10,3	7,8	0,92	0	0	0	0	0	0
Tank vehicle KWW-45 clutch pipe delivery	11,3	7,9	0,82	0	0	0	0	0	0
Drinking water delivery tap 01 clutch pipe delivery	11,4	7,7	0,92	0	0	0	0	0	0
Drinking water delivery tap 02 clutch pipe delivery	11,3	7,7	0,68	0	0	0	0	0	0
Drinking water delivery tap 03 clutch pipe delivery	11,2	7,7	0,47	0	0	0	0	0	0
Drinking water delivery tap 04 clutch pipe delivery	11,5	7,7	0,39	0	0	0	0	0	0

Bemerkungen:

Tank vehicle KWW-38 clutch pipe delivery: pH-Wert nicht messbar