

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500592804
Report October 2017

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
171019494	Drinking water Delivery Tap 1	27.10.2017	09:20	15,2	colorless, clear	0,60	7,46	0	0	0	0	0	0
171019495	Drinking water Delivery Tap 2	27.10.2017	09:25	15,2	colorless, clear	0,66	7,50	0	0	0	0	0	0
171019496	Drinking water Delivery Tap 3	27.10.2017	09:25	15,4	colorless, clear	0,86	7,50	0	0	0	0	0	0
171019497	Drinking water Delivery Tap 4	27.10.2017	09:30	15,2	colorless, clear	0,58	7,52	0	0	0	0	0	0
171019498	Tank vehicle KWW 32, clutch pipe delivery	27.10.2017	-	-	-	-	-	sampling not possible: tank vehicle not existent					
171019499	Tank vehicle KWW 33, clutch pipe delivery	27.10.2017	08:55	15,4	colorless, clear	0,52	7,76	0	0	0	0	0	0
171019500	Tank vehicle KWW 34, clutch pipe delivery	27.10.2017	08:10	15,6	colorless, clear	0,35	7,90	0	0	0	0	0	0
171019651	Tank vehicle KWW 35, clutch pipe delivery	27.10.2017	09:05	15,2	colorless, clear	0,52	7,74	0	0	0	0	0	0
171019652	Tank vehicle KWW 36, clutch pipe delivery	27.10.2017	09:00	14,2	colorless, clear	0,51	7,70	0	0	0	0	0	0
171019653	Tank vehicle KWW 37, clutch pipe delivery	27.10.2017	08:50	15,2	colorless, clear	0,59	7,70	0	0	0	0	0	0
171019654	Tank vehicle KWW 38, clutch pipe delivery	27.10.2017	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
171019655	Tank vehicle KWW 39, clutch pipe delivery	27.10.2017	08:40	15,6	colorless, clear	0,34	7,76	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500592804
Report October 2017**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
171019656	Tank vehicle KWW 40, clutch pipe delivery	27.10.2017	09:10	15,6	colorless, clear	0,55	7,60	0	0	0	0	0	0
171019657	Tank vehicle KWW 41, clutch pipe delivery	27.10.2017	08:50	15,2	colorless, clear	0,58	7,78	0	0	0	0	0	0
171019658	Tank vehicle KWW 42, clutch pipe delivery	27.10.2017	09:00	15,2	colorless, clear	0,54	7,80	0	0	0	0	0	0
171019659	Tank vehicle KWW 43, clutch pipe delivery	27.10.2017	08:50	15,0	colorless, clear	0,60	7,70	0	0	0	0	0	0
171019660	Tank vehicle KWW 44, clutch pipe delivery	27.10.2017	09:40	15,2	colorless, clear	0,56	7,76	0	0	0	0	0	0
171019661	Tank vehicle KWW 45, clutch pipe delivery	27.10.2017	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, October 07, 2017