

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500592804**  
**Report February 2018**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
180108785	Drinking water Delivery Tap 1	28.02.2018	09:10	8,4	colorless, clear	0,28	7,72	0	0	0	0	0	0
180108787	Drinking water Delivery Tap 2	28.02.2018	09:10	7,5	colorless, clear	0,16	7,76	0	0	0	0	0	0
180108788	Drinking water Delivery Tap 3	28.02.2018	09:15	8,6	colorless, clear	0,12	7,70	0	0	0	0	0	0
180108793	Drinking water Delivery Tap 4	28.02.2018	-	-	-	-	-	<b>sampling not possible: tap is defective</b>					
180108794	Tank vehicle KWW 33, clutch pipe delivery	28.02.2018	08:35	9,5	colorless, clear	0,50	7,86	0	0	0	0	0	0
180108795	Tank vehicle KWW 34, clutch pipe delivery	28.02.2018	08:50	8,0	colorless, clear	0,30	7,87	0	0	0	0	0	0
180108796	Tank vehicle KWW 35, clutch pipe delivery	28.02.2018	08:30	7,0	colorless, clear	0,20	7,77	0	0	0	0	0	0
180108797	Tank vehicle KWW 36, clutch pipe delivery	28.02.2018	09:30	6,2	colorless, clear	0,20	7,68	0	0	0	0	0	0
180108798	Tank vehicle KWW 37, clutch pipe delivery	28.02.2018	08:10	5,8	colorless, clear	0,20	7,84	0	0	0	0	0	0
180108799	Tank vehicle KWW 38, clutch pipe delivery	28.02.2018	-	-	-	-	-	<b>sampling not possible: tank vehicle is defective</b>					
180108800	Tank vehicle KWW 39, clutch pipe delivery	28.02.2018	-	-	-	-	-	<b>sampling not possible: tank vehicle is defective</b>					
180108851	Tank vehicle KWW 40, clutch pipe delivery	28.02.2018	08:38	4,5	colorless, clear	0,30	7,93	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500592804  
Report February 2018**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
180108852	Tank vehicle KWW 41, clutch pipe delivery	28.02.2018	09:30	5,0	colorless, clear	0,28	7,90	0	0	0	0	0	0
180108853	Tank vehicle KWW 42, clutch pipe delivery	28.02.2018	-	-	-	-	-	<b>sampling not possible: tank vehicle is defective</b>					
180108854	Tank vehicle KWW 43, clutch pipe delivery	28.02.2018	08:45	3,4	colorless, clear	0,24	7,86	0	0	0	0	0	0
180108855	Tank vehicle KWW 44, clutch pipe delivery	28.02.2018	09:00	6,8	colorless, clear	0,24	7,86	0	0	0	0	0	0
180108866	Tank vehicle KWW 45, clutch pipe delivery	28.02.2018	08:55	4,4	colorless, clear	0,18	7,80	0	0	0	0	0	0

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

**SGS INSTITUT FRESENIUS GmbH**

Taunusstein, March 07, 2018