

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report November 2018**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
180940765	Drinking water Delivery Tap 1	29.11.2018	09:20	13,2	colorless, clear	0,68	7,69	0	0	0	0	0	-
180940768	Drinking water Delivery Tap 2	29.11.2018	09:35	13,1	colorless, clear	0,94	7,68	0	0	0	0	0	0
180940777	Drinking water Delivery Tap 3	29.11.2018	09:45	13,1	colorless, clear	1,10	7,71	0	0	0	0	0	0
180940779	Drinking water Delivery Tap 4	29.11.2018	09:50	13,1	colorless, clear	0,52	7,81	0	0	0	0	0	0
180940781	Tank vehicle KWW 33, clutch pipe delivery	29.11.2018	08:50	12,3	colorless, clear	0,65	7,92	0	0	0	0	0	0
180940783	Tank vehicle KWW 34, clutch pipe delivery	29.11.2018	-	-	-	-	-	sampling not possible: tank vehicle out of order					
180940786	Tank vehicle KWW 35, clutch pipe delivery	29.11.2018	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
180940788	Tank vehicle KWW 36, clutch pipe delivery	29.11.2018	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
180940790	Tank vehicle KWW 37, clutch pipe delivery	29.11.2018	-	-	-	-	-	sampling not possible: tank vehicle out of order					
180940792	Tank vehicle KWW 38, clutch pipe delivery	29.11.2018	09:25	12,0	colorless, clear	0,60	7,96	0	0	0	0	0	0
180940794	Tank vehicle KWW 39, clutch pipe delivery	29.11.2018	08:40	12,7	colorless, clear	0,59	7,75	0	0	0	0	0	0
180940796	Tank vehicle KWW 40, clutch pipe delivery	29.11.2018	09:30	11,6	colorless, clear	0,58	7,96	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report November 2018**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
180940798	Tank vehicle KWW 41, clutch pipe delivery	29.11.2018	08:55	12,4	colorless, clear	0,60	7,96	0	0	0	0	0	0
180940800	Tank vehicle KWW 42, clutch pipe delivery	29.11.2018	08:45	13,1	colorless, clear	0,62	7,77	0	0	0	0	0	0
180940802	Tank vehicle KWW 43, clutch pipe delivery	29.11.2018	09:15	13,1	colorless, clear	0,50	7,84	0	0	0	0	0	0
180940804	Tank vehicle KWW 44, clutch pipe delivery	29.11.2018	09:30	11,1	colorless, clear	0,57	8,03	0	0	0	0	0	0
180940806	Tank vehicle KWW 45, clutch pipe delivery	29.11.2018	10:10	11,0	colorless, clear	0,62	8,01	0	0	0	0	0	0
181094237	Tank vehicle KWW 46, clutch pipe delivery	29.11.2018	09:40	13,2	colorless, clear	0,59	8,02	0	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, December 10, 2018