

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500592804  
Report October 2018**

| Sample ID | Sample designation                        | Sampling day | Sampling time | Water temperature °C | Description      | Free chlorine mg/l | pH-value | DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100 | DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100 | Escherichia coli KBE/100 ml Limit Value 0 | Coliforms KBE/100 ml Limit Value 0 | Pseudomonas aeruginosa KBE/100 ml Limit Value 0 | Enterococci KBE/100 ml Limit Value 0 |
|-----------|---|--------------|---------------|----------------------|------------------|--------------------|----------|--|--|---|------------------------------------|---|--------------------------------------|
| 180940754 | Drinking water Delivery Tap 1             | 31.10.2018   | 10:45         | 14,0                 | colorless, clear | 0,68               | 7,65     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940766 | Drinking water Delivery Tap 2             | 31.10.2018   | 10:50         | 13,4                 | colorless, clear | 0,94               | 7,64     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940769 | Drinking water Delivery Tap 3             | 31.10.2018   | 10:55         | 14,2                 | colorless, clear | 1,10               | 7,60     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940778 | Drinking water Delivery Tap 4             | 31.10.2018   | 11:00         | 14,2                 | colorless, clear | 0,52               | 7,72     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940780 | Tank vehicle KWW 33, clutch pipe delivery | 31.10.2018   | 10:20         | 12,0                 | colorless, clear | 0,65               | 7,85     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940782 | Tank vehicle KWW 46, clutch pipe delivery | 31.10.2018   | 10:30         | 13,5                 | colorless, clear | 0,56               | 7,80     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940784 | Tank vehicle KWW 35, clutch pipe delivery | 31.10.2018   | 10:04         | 13,6                 | colorless, clear | 0,66               | 7,68     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940787 | Tank vehicle KWW 36, clutch pipe delivery | 31.10.2018   | 09:45         | 10,6                 | colorless, clear | 0,65               | 7,73     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940789 | Tank vehicle KWW 37, clutch pipe delivery | 31.10.2018   | 10:35         | 8,0                  | colorless, clear | 0,57               | 7,88     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940791 | Tank vehicle KWW 38, clutch pipe delivery | 31.10.2018   | 10:24         | 12,2                 | colorless, clear | 0,60               | 7,86     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940793 | Tank vehicle KWW 39, clutch pipe delivery | 31.10.2018   | 10:06         | 12,2                 | colorless, clear | 0,59               | 7,78     | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 180940795 | Tank vehicle KWW 40, clutch pipe delivery | 31.10.2018   | 10:00         | 12,6                 | colorless, clear | 0,58               | 7,80     | 0  | 1  | 0   | 0                                  | 0   | 0                                    |

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500592804  
Report October 2018**

| Sample ID | Sample designation                        | Sampling day | Sampling time | Water temperature °C | Description      | Free chlorine mg/l | pH-value | DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml<br>Limit Value 100 | DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml<br>Limit Value 100 | Escherichia coli KBE/100 ml<br>Limit Value 0 | Coliforms KBE/100 ml<br>Limit Value 0 | Pseudomonas aeruginosa KBE/100 ml<br>Limit Value 0 | Enterococci KBE/100 ml<br>Limit Value 0 |
|-----------|---|--------------|---------------|----------------------|------------------|--------------------|----------|---|---|--|---------------------------------------|--|---|
| 180940797 | Tank vehicle KWW 41, clutch pipe delivery | 31.10.2018   | 10:12         | 11,0                 | colorless, clear | 0,60               | 7,86     | 0   | 0   | 0  | 0                                     | 0  | 0                                       |
| 180940799 | Tank vehicle KWW 42, clutch pipe delivery | 31.10.2018   | 09:40         | 13,8                 | colorless, clear | 0,62               | 7,75     | 0   | 0   | 0  | 0                                     | 0  | 0                                       |
| 180940801 | Tank vehicle KWW 43, clutch pipe delivery | 31.10.2018   | 10:40         | 10,6                 | colorless, clear | 0,50               | 7,77     | 0   | 0   | 0  | 0                                     | 0  | 0                                       |
| 180940803 | Tank vehicle KWW 44, clutch pipe delivery | 31.10.2018   | 10:16         | 10,2                 | colorless, clear | 0,57               | 7,94     | 0   | 0   | 0  | 0                                     | 0  | 0                                       |
| 180940805 | Tank vehicle KWW 45, clutch pipe delivery | 31.10.2018   | 09:30         | 13,0                 | colorless, clear | 0,62               | 7,74     | 0   | 0   | 0  | 0                                     | 0  | 0                                       |

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, November 07, 2018